



**Revision List for Certificate No.: 01/205/5517.03/22**  
**Product Tested: Safety function STO on control board**  
**within the COMBIVERT F6-K inverter**



**Safety relevant control boards to be used in inverters xxF6Kxx-xxxx**

Type Designation	Description	HW-Revision	Report-No.:	Certification Status
3KF6x30-0010	Safety function STO on control board within the COMBIVERT F6-K inverters	1B	968/M 393.01/16	Valid
3KF6x30-0011		1B	968/M 393.01/16	Valid
3KF6x30-0012		1B	968/M 393.04/17	Valid
3KF6x30-0013		1B	968/M 393.04/17	Valid
3KF6x30-0014		1B	968/M 393.06/22	Valid
3KF6x30-0015		1B	968/M 393.06/22	Valid
3KF6x30-0016		1D	968/M 393.08/23	Valid
3KF6x30-0017		1D	968/M 393.08/23	Valid
3KF6x30-0018		1D	968/M 393.08/23	Valid
3KF6x30-0019		1D	968/M 393.08/23	Valid

**Document Revision:**

Date	Rev.	Description / Changes	Author
2022-03-14	1.0	Initial creation, based on Report-No.: 968/M 393.06/22	jm/A-FS
2022-11-10	2.0	Update due to renewal of the certificate, based on Report-No.: 968/M 393.07/22	wi/A-FS
2023-11-23	3.0	Update due to new variants, based on Report-No.: 968/M 393.08/23	Ba/A-FS